

TABLE OF CONTENTS

CHAPTER 1 – INTRODUCTION	1-1
1.0 PURPOSE.....	1-1
1.1 STUDY AREA.....	1-1
1.2 PLAN ORGANIZATION.....	1-1
1.3 REQUIRED PLAN ELEMENTS AND FUNDING BENEFITS.....	1-2
1.4 PUBLIC INVOLVEMENT.....	1-5
1.4.0 <i>Advisory Committee</i>	1-5
1.4.1 <i>Additional Outreach Efforts</i>	1-5
1.5 PLAN APPROVAL AND IMPLEMENTATION.....	1-6
CHAPTER 2 – STILLAGUAMISH RIVER BASIN CHARACTERISTICS	2-1
2.0 OVERVIEW.....	2-1
2.1 LAND USE, COMMUNITIES, AND ENVIRONMENTAL CHARACTERISTICS.....	2-1
2.1.0 <i>Basin-Wide</i>	2-1
Land Use.....	2-1
Communities.....	2-2
Environmental Characteristics.....	2-7
2.1.1 <i>Unique Subbasin Characteristics</i>	2-8
North Fork.....	2-8
South Fork.....	2-8
Mainstem.....	2-8
2.2 REFERENCES.....	2-11
CHAPTER 3 - THE FUNDAMENTALS OF FLOODING	3-1
3.0 EVALUATING FLOODS.....	3-1
3.1 FLOOD TERMINOLOGY.....	3-1
3.1.0 <i>Flood Magnitude</i>	3-1
3.1.1 <i>Flood Duration</i>	3-2
3.1.2 <i>Flood Timing</i>	3-3
3.1.3 <i>Flood Designation</i>	3-3
3.2 WHAT IS THE 100-YEAR FLOOD?.....	3-5
3.3 WHAT CAUSES FLOODING?.....	3-5
3.3.0 <i>The Hydrologic Cycle</i>	3-5
3.3.1 <i>Topography and Climate</i>	3-6
Topography.....	3-6
Climate.....	3-7
3.3.2 <i>Land Management and Flooding</i>	3-9
3.3.3 <i>“Controlling” Floods</i>	3-9
3.4 GEOLOGY AND SOILS.....	3-10
3.4.0 <i>Geology</i>	3-10
3.4.1 <i>Soils</i>	3-10
3.4.2 <i>The Role of Sediment</i>	3-11
Channel Shaping.....	3-11
Sediment Sources.....	3-13
3.4.3 <i>Volcanoes</i>	3-13
3.5 REFERENCES.....	3-15

CHAPTER 4 - FLOOD WARNING AND OPERATIONS IN THE STILLAGUAMISH RIVER BASIN	4-1
4.0 INTRODUCTION.....	4-1
4.1 THE MECHANICS OF FLOOD WARNING.....	4-1
4.1.0 <i>Weather</i>	4-1
4.1.1 <i>Gages</i>	4-2
Data Collection.....	4-2
4.2 PLANNING.....	4-4
4.2.0 <i>Who's Who in Flood Planning</i>	4-4
DEM/EOC.....	4-4
Snohomish County Executive Office.....	4-5
Snohomish County Department of Public Works.....	4-5
Snohomish County Sheriff's Department.....	4-5
Fire Districts/Emergency Medical Services.....	4-5
Snohomish County Chapter-Red Cross.....	4-5
U.S. Army Corps of Engineers.....	4-5
4.2.1 <i>Flood Operations Phases at the EOC</i>	4-6
Phase I.....	4-6
Phase II.....	4-6
Phase III.....	4-7
Phase IV.....	4-7
4.3 NEW FLOOD FIGHTING TECHNIQUES.....	4-10
4.4 WHO CAN I CONTACT FOR MORE INFORMATION?.....	4-10
4.2 REFERENCES.....	4-12
CHAPTER 5 - FLOOD HISTORY	5-1
5.0 INTRODUCTION.....	5-1
5.1 STILLAGUAMISH RIVER – MAJOR HISTORIC FLOODS.....	5-1
5.1.0 <i>Main Stem Major Flood Events: 1860-1930</i>	5-1
5.1.1 <i>Major Flood Events: 1930-Present</i>	5-3
February 27, 1932 Flood.....	5-3
February 10, 1951 Flood.....	5-4
November 23, 1959 Flood.....	5-6
December 15, 1959 Flood.....	5-8
December 3, 1975 Flood.....	5-9
December 2, 1977 Flood.....	5-9
December 1979 Flood.....	5-10
November 10, 1990 Flood.....	5-10
November 24, 1990 Flood.....	5-11
November 8, 1995 Flood.....	5-12
November 29, 1995 Flood.....	5-12
February 8, 1996 Flood.....	5-13
March 19, 1997 Flood.....	5-13
5.1.2 <i>Personal Accounts</i>	5-16
5.2 REFERENCES.....	5-17
CHAPTER 6 - HISTORY OF FLOOD MANAGEMENT	6-1
6.0 HISTORICAL FLOOD MANAGEMENT – CONSTRUCTED PROJECTS.....	6-1

Table of Contents
 May 19, 2003

6.1	HISTORICAL FLOOD MANAGEMENT – STUDIES CONDUCTED.....	6-3
6.1.0	<i>Corps Studies</i>	6-3
	1930s to 1960s	6-3
	Flood Alternatives 1975.....	6-6
	Corps Reconnaissance Study 1979	6-6
	Flood Damage Reduction Study 1980	6-6
	Flood Hazard Reduction Study - 1989.....	6-7
	Reconnaissance Study: Stillaguamish River Ecosystem Restoration General Investigation—1997 6-8	
	Stillaguamish River Section 205 Small Flood Study—1999.....	6-8
	Stillaguamish River Ecosystem Restoration Final Feasibility Report and Environmental Assessment – 2000.....	6-9
6.1.1	<i>Flood Insurance and Disaster studies</i>	6-11
	Flood Insurance Study, Unincorporated Snohomish County—1983	6-11
	Other Participating NFIP Communities.....	6-11
	Reconnaissance Report of November 24, 1990 Flood	6-12
	Hazard Mitigation Study of the State of Washington after the November 1990 Floods—19916-12	
	Flood Damage Report of Residence Near Stanwood—1991	6-12
6.1.2	<i>Stanwood Storm Drainage Master PlaN – 1972</i>	6-12
6.1.3	<i>City of Stanwood Wastewater treatment Plant Capacity Study - 1987</i>	6-14
6.1.4	<i>Stanwood Hazard Mitigation Grant Request - 1996</i>	6-16
6.2	EFFECTS OF PAST FLOOD MANAGEMENT ON SALMON HABITAT AND OTHER ENVIRONMENTAL VALUES	6-17
6.2.0	<i>Habitat Requirements</i>	6-17
6.2.1	<i>Habitat Benefits of Flooding</i>	6-18
6.2.2	<i>Some Factors That Impact Habitat</i>	6-18
	Dikes/Levees.....	6-19
	Development.....	6-19
	Landslides	6-20
	Gravel Removal	6-20
6.2.3	<i>Changes in Flood Planning</i>	6-20
6.3	REFERENCES	6-21
CHAPTER 7 – ALTERNATIVES AND RECOMMENDED ACTIONS.....		7-1
7.0	EVALUATING ALTERNATIVES AND SELECTING A RECOMMENDED ACTION	7-1
7.0.1	<i>Plan Goals and Objectives</i>	7-1
7.0.2	<i>Prioritization Criteria</i>	7-2
7.0.3	<i>Project Evaluation Criteria</i>	7-2
7.1	BASIN-WIDE ALTERNATIVES AND RECOMMENDED ACTIONS	7-4
7.2	ALTERNATIVES AND RECOMMENDED ACTIONS BY SUBBASIN	7-35
7.2.0	<i>The North Fork of the Stillaguamish River</i>	7-35
7.2.1	<i>The South Fork of the Stillaguamish River</i>	7-57
7.2.2	<i>The Mainstem of the Stillaguamish River</i>	7-68
7.3	REFERENCES	7-82

Table of Contents
 May 19, 2003

RECOMMENDED ACTIONS

RECOMMENDED ACTION 1: CONDUCT A FLOOD INSURANCE RE-STUDY. 7-5

RECOMMENDED ACTION 2: RELOCATE CRITICAL FACILITIES. 7-9

RECOMMENDED ACTION 3: ESTABLISH A VOLUNTARY ELEVATION/RELOCATION PROGRAM. 7-10

RECOMMENDED ACTION 4: ANALYZE ALL COUNTY-OWNED OR MAINTAINED FLOOD CONTROL STRUCTURES.
 7-13

*RECOMMENDED ACTION 5: THE COUNTY SHOULD INVESTIGATE ENHANCING FLOOD STORAGE ON PUBLIC
 LANDS.* 7-14

*RECOMMENDED ACTION 6: ASSIST PUBLIC WITH PERMITTING REQUIREMENTS ASSOCIATED WITH
 COOPERATIVE BANK STABILIZATION PROGRAM* 7-16

*RECOMMENDED ACTION 7: CONDUCT ADDITIONAL HYDROLOGIC AND HYDRAULIC ANALYSIS OF FOREST
 PRACTICE IMPACTS ON PEAK FLOWS.* 7-19

RECOMMENDED ACTION 8: ESTABLISH A STUDY COMMITTEE TO ADDRESS FOREST PRACTICES. 7-19

*RECOMMENDED ACTION 9: THE COUNTY SHOULD PROMOTE VOLUNTARY INCENTIVES TO CONTINUE LOW
 DENSITY FLOODPLAIN USE.* 7-25

*RECOMMENDED ACTION 10: USING THE MODELING RESULTS FROM THE RFIS, CONDUCT A ZERO RISE
 FLOODPLAIN ASSESSMENT TO USE AS THE BASIS FOR CONSIDERATION OF ZERO-RISE PROVISIONS IN
 COUNTY CODE.* 7-27

RECOMMENDED ACTION 11: MAP HIGH HAZARD ZONES. 7-28

*RECOMMENDED ACTION 12: USE THE MAPPED HIGH HAZARD ZONE AS THE BASIS FOR CONSIDERATION OF
 HIGH HAZARD ZONE PROVISIONS.* 7-29

RECOMMENDED ACTION 13: DEVELOP A LANDSLIDE HAZARD HOMEOWNER EDUCATION PROGRAM. 7-31

RECOMMENDED ACTION 14: APPLY FOR THE NFIP COMMUNITY RATING SYSTEM. 7-33

RECOMMENDED ACTION 15: EVALUATE NEW FLOOD HAZARDS USING THE COMMITTEE-ADOPTED PROCESS.
 7-34

*RECOMMENDED ACTION 16: PARTICIPATE IN HABITAT RESTORATION PROJECTS THAT PROVIDE CUMULATIVE
 FLOOD REDUCTION OPPORTUNITIES.* 7-34

*RECOMMENDED ACTION 17: REESTABLISH CONNECTIVITY BETWEEN THE RIVER AND SIDE CHANNELS
 THROUGH THE WHITEHORSE TRAIL WHERE POSSIBLE.* 7-36

*RECOMMENDED ACTION 18: IMPLEMENT RESULTS OF CURRENT BEDLOAD STUDY TO ELIMINATE NEED FOR
 CONTINUED ANNUAL DREDGING.* 7-39

*RECOMMENDED ACTION 19: STABILIZE SWEDE HEAVEN BANK AND PURSUE VOLUNTARY ACQUISITION OF
 PROPERTY TO PROTECT TO COUNTY ROAD.* 7-43

RECOMMENDED ACTION 20: PURSUE VOLUNTARY ACQUISITION OF CHATHAM ACRES. 7-45

RECOMMENDED ACTION 21: IMPLEMENT A STEELHEAD HAVEN SLIDE STABILIZATION PROJECT. 7-47

*RECOMMENDED ACTION 22: COMPLETE ENGINEERING ASSESSMENT TO STABILIZE BRADLEY SITE BANK,
 IMPROVE HABITAT, AND REDUCE POTENTIAL DAMAGE TO PUBLIC INFRASTRUCTURE.* 7-49

*RECOMMENDED ACTION 23: DETERMINE FEASIBILITY OF TRAINING MAIN FLOW OF RIVER AT HAZEL
 HOLE/SKAGLAND WASHOUT THROUGH UPSTREAM ABANDONED CHANNEL.* 7-51

*RECOMMENDED ACTION 24: CONDUCT A DETAILED STUDY IN THE DEER CREEK/OSO AREA AND IMPLEMENT
 FINDINGS.* 7-54

*RECOMMENDED ACTION 25: DETERMINE FLOOD DAMAGE REDUCTION BENEFITS OF ACQUIRING SMOKES
 BROTHERS FARM.* 7-56

RECOMMENDED ACTION 26: REMOVE ONE LOG PER YEAR UNTIL BLACK CREEK SPLASH DAM DISMANTLED.
 7-59

*RECOMMENDED ACTION 27: ENSURE STABILIZATION OF GOLD BASIN LANDSLIDE MEETS PUBLIC SAFETY
 GOALS.* 7-61

Table of Contents
May 19, 2003

RECOMMENDED ACTION 28: WHEN REQUESTED BY ROBE VALLEY COMMUNITY THROUGH COOPERATIVE BANK STABILIZATION PROGRAM, WORK COOPERATIVELY TO STABILIZE BANK..... 7-65

RECOMMENDED ACTION 29: END FORMAL MAINTENANCE AGREEMENT ON THE ROBE HILL DIKE AND DETERMINE WHETHER TO REMOVE, MODIFY, OR LEAVE DIKE AS IS..... 7-67

RECOMMENDED ACTION 30: PROVIDE IMPROVED FLOOD WARNING ON THE MAINSTEM. 7-70

RECOMMENDED ACTION 31: CONDUCT AN AVULSION RISK ASSESSMENT OF THE DIKE ROAD DIKE AND BERM AND IMPLEMENT FINDINGS. 7-74

RECOMMENDED ACTION 32: IMPLEMENT THE PREFERRED ALTERNATIVES IN THE CORPS SECTION 205 STANWOOD AREA FLOOD CONTROL STUDY 7-76

RECOMMENDED ACTION 33: INVESTIGATE METHODS FOR FLOOD HAZARD REDUCTION BENEFITS AS PART OF THE RESTORATION ACTIVITIES IN PORTAGE CREEK. 7-77

RECOMMENDED ACTION 34: ADDRESS UPLAND STORMWATER IMPACTS TO LOWER CHURCH CREEK..... 7-80

Table of Contents
 May 19, 2003

FIGURES

FIGURE 1-1: VICINITY MAP FOR SNOHOMISH, WASHINGTON..... 1-3
 FIGURE 1-2: STILLAGUAMISH RIVER BASIN IN SNOHOMISH COUNTY, WASHINGTON..... 1-4

FIGURE 2-3: STILLAGUAMISH FLOOD CONTROL DISTRICT BOUNDARY..... 2-5
 FIGURE 2-4: STILLAGUAMISH RIVER CLEAN WATER DISTRICT BOUNDARY..... 2-6
 FIGURE 2-5: MAINSTEM STILLAGUAMISH RIVER..... 2-10

FIGURE 3-6: FLOOD DURATION HYDROGRAPHS..... 3-2
 FIGURE 3-7: PEAK FLOWS ON THE NORTH FORK STILLAGUAMISH RIVER (GAGE #12177000)..... 3-4
 FIGURE 3-8: CONCEPTUAL HYDROLOGIC CYCLE IN THE STILLAGUAMISH RIVER BASIN..... 3-6
 FIGURE 3-9: AVERAGE TEMPERATURE AND RAINFALL AT DARRINGTON AND EVERETT..... 3-8
 FIGURE 3-10: SURFICIAL GEOLOGY OF THE STILLAGUAMISH RIVER BASIN..... 3-12

FIGURE 4-11: LOCATIONS OF GAGES ON THE STILLAGUAMISH RIVER..... 4-3
 FIGURE 4-12: FLOOD PATTERNS ON THE MAINSTEM STILLAGUAMISH RIVER..... 4-9
 FIGURE 4-13: NEW FLOOD FIGHTING TECHNIQUE USING INTERLOCKING PANELS..... 4-10

FIGURE 5-14: FEBRUARY 27, 1932 - EAST STANWOOD, WASHINGTON..... 5-4
 FIGURE 5-15: FEBRUARY 10, 1951 - AERIAL VIEW OF STANWOOD LOOKING WEST..... 5-5
 FIGURE 5-16: FEBRUARY 10, 1951 FLOOD HYDROGRAPH AT ARLINGTON, WASHINGTON (CORPS 1967). .
 5-6
 FIGURE 5-17: NOVEMBER 1959 - EFFORTS TO REPAIR BREACH ON NORTH SIDE OF IRVINE SLOUGH. . 5-7
 FIGURE 5-18: NOVEMBER 1959 - CHANNEL CUT THROUGH DIKE ON NORTH SIDE OF THE OLD STILLY,
 DISCHARGING TRAPPED WATER INTO THE STILLAGUAMISH..... 5-7
 FIGURE 5-19: NOVEMBER 1959 - AERIAL VIEW OF STANWOOD LOOKING WEST..... 5-8
 FIGURE 5-20: NOVEMBER 1959 - AERIAL VIEW OF STANWOOD..... 5-8
 FIGURE 5-21: DECEMBER 1977 FLOOD - AERIAL PHOTOGRAPHS AT STANWOOD (CORPS)..... 5-10
 FIGURE 5-22: MARCH 19, 1997 FLOOD - A FARMHOUSE AND OUTBUILDINGS STRANDED IN THE VALLEY.
 5-14
 FIGURE 5-23: MARCH 19, 1997 FLOOD - FLOODING IN THE FLATS BETWEEN ARLINGTON AND STANWOOD.
 5-15
 FIGURE 5-24: MARCH 19, 1997 FLOOD - FLOODED VEHICLES IN THE STANWOOD PARK-AND-RIDE LOT. ..
 5-15

FIGURE 6-25: PUMP STATION AT MOUTH OF IRVINE SLOUGH..... 6-13
 FIGURE 6-26: ACCESS ROAD CROSSING IRVINE SLOUGH AT THE NE CORNER OF THE WWTP..... 6-14
 FIGURE 6-27: CULVERT THROUGH ACCESS ROAD FOR STORMWATER CONVEYANCE..... 6-15
 FIGURE 6-28: AERIAL PHOTOGRAPH OF THE SEVEN CULVERTS AT THE SE CORNER OF THE WWTP
 (1991)..... 6-16

FIGURE 7-29: CRITICAL FACILITIES ON THE MAINSTEM STILLAGUAMISH RIVER..... 7-8
 FIGURE 7-30: FLOOD FRINGE AND FLOODWAY ZONING..... 7-21
 FIGURE 7-31: CHANNEL CHANGES IN VERLOT REACH (1965 CHANNEL TRACED TO 2001 ORTHOPHOTO).
 7-63
 FIGURE 7-32: FLOW PATTERNS IN MAINSTEM STILLAGUAMISH BASIN..... 7-69
 FIGURE 7-33: DIKE ROAD DIKE AND SPLIT FLOW CHANNEL ON THE MAINSTEM STILLAGUAMISH. 7-73
 FIGURE 7-34: CHURCH CREEK WATERSHED..... 7-81

Table of Contents
May 19, 2003

TABLES

TABLE 1-1: STILLY FLOOD PLAN ADVISORY COMMITTEE MEMBERS.....	1-6
TABLE 3-2: STILLAGUAMISH RIVER PEAK FLOWS EXTENDED THROUGH 1998.....	3-4
TABLE 4-3: FLOOD INFORMATION SOURCES.....	4-11
TABLE 5-4: HISTORICAL FLOOD EVENTS ON THE MAINSTEM STILLAGUAMISH RIVER.....	5-2
TABLE 5-5: LARGEST PEAK FLOODS ON THE MAINSTEM STILLAGUAMISH RIVER FROM 1930S TO PRESENT.....	5-2
TABLE 6-6: CHRONOLOGY OF CONSTRUCTED PROJECTS ON THE STILLAGUAMISH RIVER AND SURROUNDING AREA.....	6-2
TABLE 6-7: PREVIOUS CORPS FLOOD MANAGEMENT ALTERNATIVES (1930S – 1960S).....	6-5
TABLE 6-8: CHRONOLOGY OF FLOOD MANAGEMENT STUDIES AND RESULTING RECOMMENDATIONS.....	6-7
TABLE 6-9: PREVIOUS CORPS FLOOD MANAGEMENT ALTERNATIVES (1970S – 1980S).....	6-10
TABLE 7-10: GOALS AND OBJECTIVES OF THE STILLY FLOOD PLAN.....	7-1
TABLE 7-11: EXISTING FLOODPLAIN PROPERTY USE.....	7-22
TABLE 7-12: LAND USE AND POTENTIAL FUTURE FLOODPLAIN DEVELOPMENT.....	7-23
TABLE 7-13: SUMMARY OF REPAIR COSTS FOR THE OSO LEVEE (RIGHT BANK).....	7-52
TABLE 7-14: ESTIMATED CHANNEL CHANGES AT SELECT LOCATIONS IN VERLOT SINCE 1965.....	7-62
TABLE 7-15: ESTIMATED REPAIRS COSTS FOR DIKE ROAD DIKE, BERM, AND ROAD SINCE 1990.....	7-71